

**CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
LOS ANGELES REGION**

101 CENTRE PLAZA DRIVE
MONTEREY PARK, CA 91754-2156
(213) 266-7500
FAX (213) 266-7600



May 22, 1997

Mr. Michael Young
Integrated Environmental Services, Inc.
3990 Westerly Place, Suite 210
Newport Beach, CA 92660

**ADDENDUM TO SOIL STOCKPILE REPORT, PARCEL A, REPORT No.1, McDONNELL
DOUGLAS C-6 FACILITY DEMOLITION - LOS ANGELES, CALIFORNIA (FILE NO.
100.315)**

We have received and reviewed the Addendum to the Soil Stockpile Report for Parcel A, at the McDonnell Douglas C-6 Facility in Los Angeles, dated May 19, 1997. The report presents the results of the PCB and SVOC sampling performed on stockpiles B37-RE-1 and B37-RE-2. Staff also discussed the report with Montgomery Watson's geologist, during a site visit, on May 20, 1997. Based on the above, we have no objections to MDRC's request to use the two referenced soil stockpiles, with the exception of the northern 36 cubic yards from B37-RE-2, as excavation backfill.

If you have any questions or comments regarding the above, please contact me at (213) 266-7550.

A handwritten signature in cursive script, appearing to read 'J.E. Ross'.

J.E. ROSS, P.E., Unit Chief
Site Cleanup Unit

cc: Ms. Karen Baker, DTSC, Long Beach
Ms. Debbie Oudiz, Office of Scientific Affairs
Mr. Anand Rege, DTSC, Long Beach
Mr. Fred Strauss, Montgomery Watson, Inc.
Mr. John Johnson, Lockheed Martin
Mr. Jeff Dhont, Federal EPA